



PANACA / LINCOLN COUNTY AIRPORT

Pavement Condition


The average inspected Pavement Condition Index (PCI) for all of the airfield pavements was **95**. The runway had an average inspected PCI of **95** and was above the desired minimum service level (MSL) of **60**.

Maintenance Needs


No features were identified for maintenance.

Capital Needs

No pavement features were below the MSL when inspected, and no features are projected to reach MSL within 5 years of the inspection.




LINCOLN COUNTY AIRPORT
2009 PCI Inspection



PCI LEGEND

100-86	Excellent	Green
85-71	Very Good	Blue
70-56	Good	Cyan
55-41	Fair	Yellow
40-26	Poor	Orange
25-11	Very Poor	Pink
10-0	Failed	Red



PCI HISTORY

FEATURE	PCI	TYPE	AGE	DET. RATE
105	100	AC/AC	0	N/A
205	100	AC	0	N/A
4105	95	AC/AC	2	2.5
9105	95	AC/AC	2	2.5

VIABLE CIP ACTIONS

FEATURE	ACTION YR	ACTION	COST (\$)	LIFE EXT
105	NONE	No Action	0	0
205	NONE	No Action	0	0
4105	NONE	No Action	0	0
9105	NONE	No Action	0	0
